

0.038

2-2-87

File



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84143-1003 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Dec. 16, 1987
10:00 a.m. to 4:00 p.m.

Permittee and/or Operators Name: Co-Op Mining Company
Business Address: P.O. Box 1245 Huntington, Utah 84528
Mine Name: Bear Canyon Permit Number: ACT/015/025
Type of Mining Activity: Underground ☒ Surface ☐ Other ☐
County: Emery
Company Official (s): Gerald Hansen and Mel Coonrod
State Official(s): Harold G. Sandbeck
Partial: ☐ Complete: ☒ Date of Last Inspection: Nov. 30, 1987
Weather Conditions: Cloudy and snowy
Acreage: Permitted 900 Disturbed 10 Regraded Seeded Bonded 10
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION Dec. 16, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Gerald Hansen (Co-Op) and Mel Coonrod (operator's consultant) accompanied the undersigned inspector on this complete. The ground was frozen and snow covered.

NOV 87-27-1-2, which was issued on September 25, 1987, was terminated on December 11, 1987 (effective date).

1. PERMITS:

Bonding Status--A \$256,122.00 letter of credit is posted with Sandy Bank of Utah effective October 23, 1988.

2. SIGNS AND MARKERS:

Perimeter markers were seen with the required orange tips.

4b. DIVERSIONS:

Since the last inspection on November 30, 1987, the operator cleared the ditches which required preventive maintenance, and the trash rack for the 24-inch culvert has not been completed at this time. This culvert presently has a trash rack, but a larger one is needed. Two ditch blockages were cleared on site and inspected before the undersigned inspector left the site. A culvert at the main entrance gate is half full and requires cleaning as soon as weather permits. Presently, the culvert is frozen solid with sediment and water but still functional.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

The ponds were inspected and found to be in compliance. The pond inspections for the fourth quarter 1987 were checked.

Copy of this Report:

Mailed to: Gerald Hansen, Co-Op; Brian Smith, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Dec. 22, 1987